

### State of Utah

#### Department of Natural Resources

MICHAEL R. STYLER
Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director  $\begin{array}{c} {\rm JON~M.~HUNTSMAN,~JR.} \\ {\rm \it Governor} \end{array}$ 

GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
Company	Gregg Galecki Environmental Coordinator	
OGM	Steve Demczak Environmental Scientist III	

## **Inspection Report**

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, October 25, 2005
Start Date/Time:	10/25/2005 10:00:00 PM
End Date/Time:	10/25/2005 2:00:00 PM
Last Inspection:	Monday, September 19, 2005

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 779

Accepted by: pgrubaug 11/14/2005

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: **SKYLINE MINE** 

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

#### Mineral Ownership Types of Operations

10,	374.00	<b>Total Permitted</b>	✓ Federal	✓ Underground
	79.12	Total Disturbed	✓ State	☐ Surface
		Phase I	☐ County	Loadout
		Phase II	<b>✓</b> Fee	Processing
		Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

#### Permit Conditions:

- 1) Submit Water Monitoring data in electronic format to the Division.
- 2) Canyon Fuel Co. must submit all existing studies and data for the update of the PHC as a result of the mine inflows.
- 3) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek.
- 4) Canyon Fuel Co. must have a qualified person compile and analyze past macroinvertebrate studies on Eccles Creek into one report.
- 5) Canyon Fuel Co. must initiate an update to and further evaluation of the Hydrologic and Channel-Stability Evaluation of Eccles and Mud Creek.

The permittee is meeting these permit conditions.

Permit Renewal was April 30, 2002, and expires on April 30, 2007.

The permittee has the following permiting action with the Division- a) North Lease Subsidence Mining, b) Eccles Creek/ Mud Creek Evaluation, and c) Midterm Permit Review.

Friday, November 04, 2005	Date,	
	ISPECIOI S SIGNATURE Priday, November 04, 2005	nspector's Signature Date Friday, November 04, 2005

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 25, 2005

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		<b>✓</b>	
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil	<b>✓</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>		<b>✓</b>	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	<b>✓</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>✓</b>		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 25, 2005 Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

The Mining and Reclamation Permit will expire on April 30, 2007.

#### 2. Signs and Markers

The identifications signs were inspected and complied with the R645 Coal Rules.

#### 3. Topsoil

There were no signs of wind or water erosion.

#### 4.a Hydrologic Balance: Diversions

The diversions were spot checked and open for water flow. Several of the diversions were recently cleaned out.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds and found no hazardous conditions. The mine and rail loadout sediment ponds did contain water.

#### 4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences were functioning as designed.

#### 8. Noncoal Waste

The mine site was clear of non coal waste materials.

#### 18. Support Facilities, Utility Installations

No new facilities have been constructed since the last inspection.